### J. J. Keller & Associates, Inc.® Update

The Federal Motor Carrier Safety Administration (FMCSA) has updated the list of violations used to calculate scores in the Compliance, Safety, Accountability (CSA) program, adding 63 violations, removing 4 violations, and updating the descriptions of another 34 violations. The changes went into effect with the scores issued on September 25, 2020. The additions and deletions listed below affect the violation severity tables found in the *CSA Handbook: A Complete Guide for CMV Drivers*. These and other changes will appear in the next printing of the *Handbook*.

#### **ADDED VIOLATIONS:**

**Unsafe Driving** 

Section	Description	Group	Severity	Affects Driver Score?
	Failure to comply with the Safe Clearance requirements for highway-	Dangerous		
177.804B1	rail grade crossings in 49 CFR Section 392.12	Driving	5	Υ
	Failure to comply with 49 CFR Section 392.80 Texting While			
	Operating a CMV when transporting select agents or toxins or HM			
177.804B2	requirement Placarding	Texting	10	Υ
	Failure to comply with 49 CFR Section 392.82 Using a Handheld			
	Mobile Phone While Operating a CMV when transporting select			
177.804B3	agents or toxins or HM requiring placard	Phone Call	10	Υ

**HOS Compliance** 

Section	Description	Group	Severity	Affects Driver Score?
	Motor carrier failed to ensure that the ELD automatically	Other Log/Form		
395.26B	recorded the required data elements.	& Manner	1	N

#### **Vehicle Maintenance**

Section	Description	Group	Severity	Affects Driver Score?
393.40B	Brakes - no pedal reserve	Brakes, All Others	4	Υ
393.45A-HBL	Hydraulic Brake - leaking on application	Brakes, All Others	4	N
393.47A-CD	Brake drum with external crack or crack that opens upon application	Brakes, All Others	4	N
393.47A-CR	Rotor (disc) cracked more than 75 percent of the friction surface completely through the rotor or completely through a solid rotor or completely through a structural support	Brakes, All Others	4	N
393.47A-RM	Brake rotor or drum - piece missing or in danger of falling			
	away	Brakes, All Others	4	N
393.47A-RW	Brake rotor worn to or through center vents	Brakes, All Others	4	N
393.48A-BS	Brake – Smoking	Brakes, All Others	4	Υ

# **Vehicle Maintenance (continued)**

Section	Description Group		Severity	Affects Driver Score?
393.70B1II-	Fifth wheel - any movement between components			
FWCM		Coupling Devices	3	Υ
393.70B2- ENGAGED	Kingpin not properly engaged	Coupling Devices	3	Υ
393.71J-SMU	Upper Saddlemount - Missing Fasteners, loose, cracked, or excessive movement	Coupling Devices	3	Υ
393.71K-SML	Lower Saddlemount - Missing Fasteners, loose, cracked, or excessive movement	Coupling Devices	3	Y
393.93B3	Temporary Seating - Vehicle must conform to the requirements of Federal Motor Vehicle Safety Standard No. 2071 (9571.207)	Cab, Body, Frame	2	Y
396.3A1-AR	Brake - Defective Air Reservoir	Brakes, All Others	4	N
396.3A1-	Wheels - Welded Repair on wheel other than Disc-to-Rim	Wheels, Studs,		
AWW	attachment	Clamps, Etc.	2	Υ
396.3A1-BFL	Brakes - Hydraulic Brake Failure Light missing, inoperative, or stays activated	Brakes, All Others	4	Υ
396.3A1-BPA	Brakes - Hydraulic Brake Power Assist / Power Brake Unit / Brake Backup System Inoperative	Brakes, All Others	4	N
396.3A1-CD	C-Dolly - Defective / Missing Locks - not centered	Coupling Devices	3	Υ
396.3A1-CDST	Defective coupling devices for semi-trailer.	Coupling Devices	3	Υ
396.3A1-CH	Brake - Hole in Spring Brake Housing	Brakes, All Others	4	N
396.3A1-EC	Bus - Electrical Mountings broken or unsecured	Other Vehicle Defect 3		Y
396.3A1-FA	Front Axle and any other steering components cracked/repair welded	Steering Mechanism 6		Y
396.3A1- FWMOV	Fifth wheel- Movement exceeds 1/2 inch	Coupling Devices	3	Y
396.3A1-HC	Hubs - Hub cap missing or broken	Wheels, Studs, Clamps, Etc.	2	Y
396.3A1-HS	Hub smoking	Wheels, Studs, Clamps, Etc. 2		Y
396.3A1-LC	Brake - Leak from air chamber	Brakes, All Others	4	Υ
396.3A1-MCF	Brakes - Hydraulic Fluid level in Master Cylinder low	Brakes, All Others 4		N
396.3A1-PAW	Pitman Arm - welded / missing nuts	Steering Mechanism	6	Υ
396.3A1-SGB	Steering Gear Box - welded	Steering Mechanism	6	Y
396.3A1-SSF	Sliding subframe rail defective	Steering Mechanism	6	Y
396.3A1-TC	Tire in contact with another part of the vehicle	Tires	8	Υ
396.3A1-TM	Tires - Not for Highway User used on Steering Axle	Tires		
396.3A1-TP	Tires - Use of Tire Plug or Cord	Tires	8	Υ

# **Vehicle Maintenance (continued)**

Section	Description	Group	Severity	Affects Driver Score?
	Tie Rods / Drag Links - Defective Clamps / Holes / Missing	Steering		
396.3A1-TRDL	nuts	Mechanism	6	Υ
		Steering		
396.3A1-TS	Tilt or Telescopic Steering defective	Mechanism	6	Υ
396.7A-LT	Solid item lodged between dual tires	Tires	8	Υ

# **Controlled Substances/Alcohol**

Section	Description	Group	Severity	Affects Driver Score?
	Prohibited from performing safety sensitive functions per			
390.3E	382.501(a) in the Drug and Alcohol Clearinghouse.	Alcohol Jumping OOS	10	Υ
	Driver consuming an intoxicating beverage within 4 hours			
392.5A1	before operating a motor vehicle	Alcohol	5	Υ

**Hazmat Compliance** 

Section	Description	Group	Severity	Affects Driver Score?
	Violation of US requirements for Transport Canada TDG			
171.12A	shipment	HM Other	2	N
	Type B, B(U), B(H) package not marked with radiation			
172.310D	symbol	Markings - HM	5	N
78.336-10	MC330 Protecting of Fittings	Package Integrity - HM	8	N
78.336-13	MC330 Anchoring of Tank	Package Integrity - HM	8	N
78.336-17	MC330 Metal ID Plate Marking	Package Integrity - HM	8	N
178.340-7D	MC306/307/312 ring stiffeners	Package Integrity - HM	8	N
180.352F	Failure to mark IBC periodic retest date	Package Testing - HM	7	N

## **Driver Fitness**

Section	Description	Group	Severity	Affects Driver Score?
	Operating a CMV without a valid CDL: No double- or			
383.23A2-DT	triple-trailer endorsement	License-related: High	8	Υ
	Operating a CMV without a valid CDL: No hazardous			
383.23A2-H	materials / dangerous goods endorsement	License-related: High	8	Υ
	Operating a CMV without a valid CDL: No passenger			
383.23A2-P	vehicle endorsement	License-related: High	8	Υ
	Operating a CMV without a valid CDL: Violation of air			
383.23A2-R	brake restriction	License-related: High	8	Υ
	Operating a CMV (School Bus) without a valid CDL: No			
383.23A2-S	school bus endorsement as described in 383.93(b)(5).	License-related: High	8	Υ

# **Driver Fitness (continued)**

Section	Description	Group Severity		Affects Driver Score?
383.23A2-T	Operating a CMV without a valid CDL: No Tank Vehicle endorsement	License-related: High	8	Υ
363.23A2-1	Operating a CMV with a Commercial Learner's Permit	License-related. High	0	'
	transporting passengers requiring the passenger (P)			
383.25A5I	endorsement	License-related: High	8	Υ
	Operating a CMV with a Commercial Learner's Permit			
	transporting passengers requiring the school bus (S)			
383.25A5II	endorsement	License-related: High	8	Υ
	Operating a CMV with a Commercial Learner's Permit			
383.25A6	transporting hazardous materials as defined in 9383.5	License-related: High	8	Υ
	Driver operating a CMV without proper endorsements		_	
391.11B4-DEN	or in violation of restrictions.	License-related: High	8	Υ
	Operating a property-carrying vehicle without			
204 44 44 500	possessing a valid medical certificate. Previously Cited	NA - di - di Combificado	_	V
391.41A1-FPC	on [DATE]	Medical Certificate	1	Υ
	No medical certificate in driver's possession - vision,			
391.41A1-LOC	hearing, insulin using, epilepsy or any condition causing loss of consciousness	Medical Certificate	1	Υ
391.41A1-LOC	Operating a property-carrying vehicle without	Wiedical Certificate	1	1
	possessing a valid medical certificate - no previous			
391.41A1-NPH	history.	Medical Certificate	1	Υ
	Operating a passenger-carrying vehicle without	carcar continuate	_	•
391.41A1-P	possessing a valid medical certificate.	Medical Certificate	1	Υ
	Operating a commercial motor vehicle without			
	complying with the requirements indicated on the			
391.49JCOMPLY	skill performance evaluation	Medical Certificate	1	Υ

## **REMOVED VIOLATIONS:**

BASIC	Section	Description
Vehicle Maintenance 393.61(a)		Inadequate or missing truck side windows
Vehicle Maintenance	393.86	No or improper rear-end protection
Vehicle Maintenance	393.87	Warning flag required on projecting load
HM Compliance	180.407(c)	Failing to periodically test and inspect cargo tank

Due to the constantly changing nature of the CSA program, a website has been established to keep you informed of any forthcoming changes affecting the *CSA Handbook*. Go to **jjkeller.com/492h** for the latest information.